

## Johnson Bethea (CEX)

---

**From:** Turner Bob  
**Sent:** 07 June 2019 13:53  
**To:** dcscan@sheffield.gov.uk  
**Subject:** FW: 17/04673/OUT Highway arrangements.

Please add 'Highways DC - additional comments' consultee to casefile 17/04673/OUT

---

**From:** Dodson Matthew  
**Sent:** 07 June 2019 11:11  
**To:** Turner Bob  
**Subject:** 17/04673/OUT Highway arrangements.

Bob,

As discussed, the highway elements in the draft 106 agreement (Bus stop upgrades/MOVA improvements/Pedestrian crossing) should be omitted as they are to be covered by section 278 agreement.

I have reviewed conditions 16 & 17 and I am satisfied that the wording reflects the highway requirements.

Can you confirm that directive D032 is included on the list of directives please?

Regards,

Matt Dodson  
Senior Highway Development Technician  
5<sup>th</sup> floor  
Howden House  
1 Union Street  
Sheffield  
S1 2SH

## Johnson Bethea (CEX)

---

**From:** Turner Bob  
**Sent:** 06 June 2019 17:45  
**To:** dcscan@sheffield.gov.uk  
**Subject:** FW: Carr Road Accident data

Please add 'Highways DC – accident data' consultee response to casefile 17/04673/OUT

---

**From:** Dodson Matthew  
**Sent:** 27 February 2019 11:54  
**To:** Turner Bob  
**Subject:** Carr Road Accident data

Bob,

I have the 5 year data for Carr Road. I asked for data to include the Hollin Busk junction to the junction with Wood Royd Road. There is 1 recorded accident, dated 14/10/2017, that involved a vehicle travelling down Carr Road colliding with a vehicle turning right into Wood Royd Road. The severity was recorded as slight.

Regards,

Matt Dodson  
Senior Highway Development Technician  
5<sup>th</sup> floor  
Howden House  
1 Union Street  
Sheffield  
S1 2SH  
(0114) 2039648